



NATIONAL TRANSPORTATION SAFETY BOARD
Investigative Hearing

Norfolk Southern Railway general merchandise freight train 32N
derailment with subsequent hazardous material release and fires,
in East Palestine, Ohio, on February 3, 2023

GROUP	D
EXHIBIT	
34	

Agency / Organization

NTSB

Title

Figure 1, Hazardous Materials Group Chair's Factual Report. Labeled derailment photographs, west trailing cars (top), east leading cars (bottom), February 5, 2023.

Line #	Car No.	Car Type
25	GPLX 75465	Hopper
26	ECUX860375	Hopper
27	UTLX 684543	DOT-117J100W
28	TILX 402025	DOT-105J300W
29	OCPX 80235	DOT-105J300W
30	OCPX 80179	DOT-105J300W
31	GATX 95098	DOT-105J300W
32	RACX 51629	DOT-111A100W1
33	LYBX 5191	DOT-117J100W
34	RACX 51435	DOT-111A100W1
35	UTLX 671772	DOT-111A100W1
36	SHPX 211226	DOT-111S100W1
37	TILX 331319	Hopper
38	DOWX 73168	DOT-111S100W1
39	ROIX 57036	Hopper
40	NCUX 40057	Hopper
41	UTLX 100055	DOT-111A100W1
42	XOMX 110664	AAR-211A100W1
43	UTLX 684798	DOT-117J100W
44	UTLX 671310	DOT-111A100W1
45	CERX 30072	DOT-111A100W1
46	SHPX 211106	DOT-111S100W1
47	NATX 231335	DOT-111A100W1
48	UTLX 671913	DOT-111A100W1
49	NATX 35844	DOT-105J300W
50	UTLX 205907	DOT-111A100W1
51	UTLX 661296	DOT-111A100W1
52	COCX 287059	DOT-111A100W1
53	ROIX 59396	Hopper
54	ROIX 57782	Hopper
55	OCPX 80370	DOT-105J300W
56	TBOX 640019	Box Car
57	BKTY 152621	Box Car
58	LINX 7278	Box Car
59	DPRX 259013	DOT-111A100W1
60	DPRX 258671	DOT-111A100W1
61	XOMX 110236	Hopper
62	ELTX 3421	Hopper

- Non-Hazardous Commodity Released/Burned
- Hazardous Commodity Released/Burned
- VCM Vent and Burn

