



NATIONAL TRANSPORTATION SAFETY BOARD
Investigative Hearing

Norfolk Southern Railway general merchandise freight train 32N
derailment with subsequent hazardous material release and fires,
in East Palestine, Ohio, on February 3, 2023


GROUP	D
EXHIBIT	
49	

Agency / Organization

NTSB

Title

**Figure 47, Hazardous Materials Group Chair's Factual Report. OCPX80235 pressure plate showing PRD and angle valves. The aluminum liquid and vapor valve handwheels were missing, a solidified mass of melted aluminum surrounds the base of a liquid valve. The PRD top guide contained loose aluminum debris.
March 15, 2023.**



Missing Aluminum Angle
Valve Handwheels

Aluminum Debris

Aluminum Mass