


NATIONAL TRANSPORTATION SAFETY BOARD Investigative Hearing

Norfolk Southern Railway general merchandise freight train 32N derailment with subsequent hazardous material release and fires, in East Palestine, Ohio, on February 3, 2023



Agency / Organization

Norfolk Southern Railway

Title

Vinyl Chloride Tank Car Temperature Measurement Spreadsheet

| Tank Car pressures by the hour | | | | | |
|--------------------------------|------------|-----------|-----------|-----------|-----------|
| TIME | TILX402025 | OCPX80235 | OCPX80179 | GATX95098 | OCPX80370 |
| 1600 | 65 | 65 | 65 | 67 | 135 |
| 1700 | | | | | 138 |
| 1800 | | | | | 136 |
| 1900 | | | | | 136 |
| 2000 | | | | | 130 |
| 2100 | | | | | 130 |
| 2200 | | | | | 130 |
| 2300 | | | | | 131 |
| 2400 | 65 | 65 | 65 | 67 | 139 |
| 0100 | 65 | 65 | 65 | 67 | 129 |
| 0200 | | | | | |
| | | | | | |
| | | | | | |