

Harlem- Manhattan - NY - Video captured about the time of accident on March 12 2014 -2

Statement: Video -2 shows time of explosion at: 1644 Park Avenue, about 9:30 a.m. This was video captured on East 116th Street, indirectly opposite: 95 East 116th Street, and 1640 Park Avenue. Show members of the public walking pass the camera, on the south, East-116th side-walk, on a normal day. Being East of Park Avenue, video show the Metro-North Commuter Railroad's, Rail-Cars, drove pass. Show a woman crossed from the south, side-walk of East 116 Street, then entered; 116 Deli Store, she was there when explosion occurred, as seen in another video. Shows explosion debris' flying onto East 116th Street, up to opposite roadway side-walk; show members of the public, confused, running back and forth, on the side-walk, south-side of the explosion; some stopped to take pictures, video, and made phone calls. Video show a woman, carrying a baby, initially trapped behind the hallway main entrance door to, 1642 Park Avenue, seen in another video, running east on the south-side side-walk on East 116th Street. The woman carrying a baby was also pregnant. Signs of confusion continued with members of the public, as the police came by, and the fire department vehicles. The pregnant woman with a baby stopped, spoke briefly to a lady officer, in union. Soon the police came and condole off the areas including the south side-walk on East 116th Street.