



Vehicle Attachment – Idaho State Police Post-Crash Vehicle Inspections

Boise, ID

HWY18FH015

(5 pages)

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

IDAHO STATE POLICE/COMMERCIAL VEHICLE SAFETY
 700 S STATFORD RD
 MERIDIAN, ID 83642-6202
 PHONE: (208) 884-7220 FAX: (208) 884-7192
 EMAIL: CVSMail@ISP.IDAHO.GOV

Report Number: ID3100006357
Inspection Date: 06/19/2018
Start: 6:10 AM MT **End:** 10:24 AM MT
Inspection Level: II - Walk-Around
HM Inspection Type: None

KRUJEX FREIGHT TRANSPORT CORP
 13215-C8 SE MILL PLAIN BLVD #1
 VANCOUVER, WA 98684
USDOT#: 02314662 **Phone#:** (360)524-3887
MC/MX#: 790202 **Fax#:**
State#:

Driver: TSAR, ILLYA D
License#: [REDACTED] **State:** NY
Date of Birth: [REDACTED]
CoDriver:
License#: **State:**
Date of Birth:

Location: EB
Highway: I 84
County: ADA, ID

MilePost: 47
Origin: YAKIMA, WA
Destination: METHUEN, MA

Shipper:
Bill of Lading:
Cargo: APPLES

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	CVSA #	New CVSA #	OOS#
1	TT	VOLV	2019	OR	YAIU484	101204	4V4NC9EH5KN905327				
2	ST	GDAN	2015	OR	HV28430	3131	1GRAA0621FW701488	68,000			

BRAKE ADJUSTMENTS: No Brake Measurements Required For Level 2

VIOLATIONS

Vio Code	Section	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
393.75A3	393.75(a)(3)	1	Y		U	Y	Tire-flat and/or audible air leak: tires flat and damaged due to fire
393.60C	393.60(c)	1	N		N	Y	Damaged or discolored windshield: windshield damaged
393.78	393.78	1	Y		U	Y	Windshield wipers inoperative/defective: wipers inop
393.95A	393.95(a)	1	N		N	Y	No/discharged/unsecured fire extinguisher: no extinguisher
393.95F	393.95(f)	1	N		N	Y	No / insufficient warning devices: no triangles
399.207	399.207	1	N		N	Y	Vehicle access requirements violations: vehicle access damaged in fire
396.3A1BOS	396.3(a)(1)	1	Y		U	Y	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination: all truck brakes damaged in fire
393.45DLUV	393.45(d)	1	Y		U	Y	Brake Connections with Leaks Under Vehicle: air lines damaged in fire and don't hold air
396.3A1B	396.3(a)(1)	1	Y		U	Y	Brakes (general) Explain:: failed air loss rate
393.207A	393.207(a)	1	Y		U	Y	Axle positioning parts defective/missing: axle positioning parts damaged in the crash and fire, shifted from original position
393.205A	393.205(a)	1	Y		U	Y	Wheel/rim cracked or broken: wheels damaged in fire
393.9	393.9(a)	1	Y		U	Y	Inoperable Required Lamp: no operable lamps, system damaged in fire
396.3A1-LLEAK	396.3(a)(1)	1	Y		U	Y	A liquid fuel system with a dripping leak at any point.: fuel tanks damaged in the fire, melted away portions of the tanks
393.9	393.9(a)	2	Y		U	Y	Inoperable Required Lamp: no operable

Report Prepared By:
 JESSE AVERY

Badge #:
 3378

Copy Received By:
 ILLYA TSAR

Page 1 of 2



02314662 ID ID3100006357

X

X

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

IDAHO STATE POLICE/COMMERCIAL VEHICLE SAFETY
700 S STATFORD RD
MERIDIAN, ID 83642-6202
PHONE: (208) 884-7220 FAX: (208) 884-7192
EMAIL: CVSMail@ISP.IDAHO.GOV

Report Number: ID3100006357
Inspection Date: 06/19/2018
Start: 6:10 AM MT End: 10:24 AM MT
Inspection Level: II - Walk-Around
HM Inspection Type: None

KRUJEX FREIGHT TRANSPORT CORP
13215-C8 SE MILL PLAIN BLVD #1
VANCOUVER, WA 98684
USDOT#: 02314662 Phone#: (360)524-3887
MC/MX#: 790202 Fax#:
State#:

Driver: TSAR, ILLYA D
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:
State: NY
State:

Table with 8 columns: Vio Code, Section, Unit, OOS, Citation #, Verify, Crash, Violations Discovered. Contains 5 rows of violation data.

HazMat: No HM Transported. Placard: No Cargo Tank:

Special Checks: Traffic Enforcement: Post Crash;

Pursuant to the authority contained in I.C. 67 2901A (IDAPA 11.13.01.018 and 11.13.01.019), I hereby notify and declare ILLYA TSAR to be "OUT OF SERVICE." No motor carrier shall permit or require this driver to operate any motor vehicle until: 8/20/18 2024 MT.

I certify that the violations listed in the "OUT OF SERVICE" section of this report have been satisfactorily completed as of the date indicated. Failure to return this report with the required certification can result in penalties up to \$1,000 per day for each day the violation continues, up to a total of \$10,000.

Signature Of Repairer X: Facility: Date:

CARRIER CERTIFICATION: The undersigned certifies that all violations on this report have been corrected and action taken to ensure compliance with the Idaho Code, Motor Carrier Safety and HM Regulations, insofar as they are applicable to motor carriers and drivers. This certification MUST BE SIGNED by the Motor Carrier and RETURNED WITHIN 15 DAYS. Failure to make all repairs listed on this notice may subject the driver to disqualification and/or fines up to \$2,500.00. Employers may also be subject to fines up to \$10,000.00.

Signature Of Motor Carrier X: Title: Date:

Report Prepared By:
JESSE AVERY

Badge #:
3378

Copy Received By:
ILLYA TSAR



X

X

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

IDAHO STATE POLICE/COMMERCIAL VEHICLE SAFETY
700 S STATFORD RD
MERIDIAN, ID 83642-6202
PHONE: (208) 884-7220 FAX: (208) 884-7192
EMAIL: CVSMail@ISP.IDAHO.GOV

Report Number: ID3100006356
Inspection Date: 06/17/2018
Start: 1:48 AM MT End: 01:47 AM MT
Inspection Level: II - Walk-Around
HM Inspection Type: None

ZHUK EXPRESS LLC
PO BOX 40
OREGON CITY, OR 97045-0040
USDOT#: 02888227 Phone#: [REDACTED]
MC/MX#: 969860 Fax#: [REDACTED]
State#: [REDACTED]

Driver: ZHUK, ROMAN I
License#: [REDACTED] State: WA
Date of Birth: [REDACTED]
CoDriver:
License#: [REDACTED] State: [REDACTED]
Date of Birth: [REDACTED]

Location: EB MilePost: 47 Shipper: STEMILT
Highway: I 84 Origin: WENATCHEE, WA Bill of Lading: 838489
County: ADA, ID Destination: MONROE TOWNSHIP Cargo: PEARS

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	CVSA #	New CVSA #	OOS#
1	TT	VOLV	2003	WA	[REDACTED]	2006	4V4NC9TG33N[REDACTED]	50,350			
2	ST	GDAN	2008	WA	[REDACTED]	2838	1GRAA06288W[REDACTED]	68,000			

BRAKE ADJUSTMENTS: No Brake Measurements Required For Level 2

VIOLATIONS

<u>Vio Code</u>	<u>Section</u>	<u>Unit</u>	<u>OOS</u>	<u>Citation #</u>	<u>Verify</u>	<u>Crash</u>	<u>Violations Discovered</u>
393.9	393.9(a)	2	Y		U	Y	Inoperable Required Lamp: no operable lamps
393.45DLUV	393.45(d)	2	Y		U	Y	Brake Connections with Leaks Under Vehicle: air leaks due to fire
393.75A3	393.75(a)(3)	2	Y		U	Y	Tire-flat and/or audible air leak: tires flat/damaged in fire
396.3A1	396.3(a)(1)	2	Y		U	Y	Inspection, repair and maintenance of parts & accessories: external hubs damaged in fire
393.201A	393.201(a)	2	Y		U	Y	Frame cracked / loose / sagging / broken: frame and trailer body damaged in fire
393.86A1	393.86(a)(1)	2	N		N	Y	Rear Impact Guards Required - trailer manufactured on or after January 26, 1998: rear impact guard damaged
396.3A1-LLEAK	396.3(a)(1)	2	Y		U	Y	A liquid fuel system with a dripping leak at any point.: reefer fuel tank damaged in fire
393.11	393.11	1	N		N	Y	No or defective lighting devices or reflective material as required: no reflective material on mud flap area, damaged in fire
393.75A3	393.75(a)(3)	1	Y		U	Y	Tire-flat and/or audible air leak: tires melted in fire, not able to hold air
393.9	393.9(a)	1	Y		U	Y	Inoperable Required Lamp: all lamps inop
396.3A1BOS	396.3(a)(1)	1	Y		U	Y	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination: brakes inop due to fire
396.3A1B	396.3(a)(1)	1	Y		U	Y	Brakes (general) Explain:: fail air loss rate
393.45DLUV	393.45(d)	1	Y		U	Y	Brake Connections with Leaks Under Vehicle: air lines damaged in fire, red line behind TT melted and has bubble coming out of it

Report Prepared By:
JESSE AVERY

Badge #:
3378

Copy Received By:
ROMAN ZHUK

Page 1 of 2



02888227 ID ID3100006356

X _____

X _____

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

IDAHO STATE POLICE/COMMERCIAL VEHICLE SAFETY
700 S STATFORD RD
MERIDIAN, ID 83642-6202
PHONE: (208) 884-7220 FAX: (208) 884-7192
EMAIL: CVSMail@ISP.IDAHO.GOV

Report Number: ID3100006356
Inspection Date: 06/17/2018
Start: 1:48 AM MT End: 01:47 AM MT
Inspection Level: II - Walk-Around
HM Inspection Type: None

ZHUK EXPRESS LLC
PO BOX 40
OREGON CITY, OR 97045-0040
USDOT#: 02888227 Phone#: (503)810-3117
MC/MX#: 969860 Fax#:
State#:

Driver: ZHUK, ROMAN I
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:
State: WA
State:

Table with 8 columns: Vio Code, Section, Unit, OOS, Citation #, Verify, Crash, Violations Discovered. Contains 4 rows of violation data.

HazMat: No HM Transported. Placard: No Cargo Tank:

Special Checks: Post Crash;

Pursuant to the authority contained in I.C. 67 2901A (IDAPA 11.13.01.018 and 11.13.01.019), I hereby notify and declare ROMAN ZHUK to be "OUT OF SERVICE." No motor carrier shall permit or require this driver to operate any motor vehicle until: 6/20/18 2033 MT and valid in OR.

I certify that the violations listed in the "OUT OF SERVICE" section of this report have been satisfactorily completed as of the date indicated. Failure to return this report with the required certification can result in penalties up to \$1,000 per day for each day the violation continues, up to a total of \$10,000.

Signature Of Repairer X: Facility: Date:

CARRIER CERTIFICATION: The undersigned certifies that all violations on this report have been corrected and action taken to ensure compliance with the Idaho Code, Motor Carrier Safety and HM Regulations, insofar as they are applicable to motor carriers and drivers. This certification MUST BE SIGNED by the Motor Carrier and RETURNED WITHIN 15 DAYS. Failure to make all repairs listed on this notice may subject the driver to disqualification and/or fines up to \$2,500.00. Employers may also be subject to fines up to \$10,000.00.

Signature Of Motor Carrier X: Title: Date:

Report Prepared By:
JESSE AVERY

Badge #:
3378

Copy Received By:
ROMAN ZHUK



X

X