

LMSID	OPAR_OPERATING_AREA_ID	PILR_CRTE_YR	PISC_PILR_SOURCE_ID	PILR_ID_SEQ	INIT_LEAK_DTE	INIT_A_LEAK_DTE	INIT_B_LEAK_DTE	INIT_C_LEAK_DTE	PICL_PILR_CLASS_CDE
72021020451		7	2021 02	0451	02/16/2021			02/16/2021	R
72022010047		7	2022 01	0047	01/06/2022		01/06/2022		R

PLSB_POLITICAL_SUB_ID	PIEL_HOUSE_BLDG_NUM	PIEL_ADDR_DIRECTION	PIEL_STREET_NME	PIEL_STREET_TYPE	PIEL_GENERAL_LOCATION_TXT	PRES_PRESSURE_CDE	SUSP_MAIN_MAIN_OID
220 77		S	2nd	Ave	Cherry	Medium	73183
220 77		S	2nd	Ave	Franklin St	Medium	73178

SUSP_MAIN_OPERATING_AREA_ID	SUSP_MAIN_STUDY_CDE	SUSP_MAIN_SEQ_NUM	SUSP_MAIN_SUB_ID	COMMENT_TXT	LKHS_CRTE_TS	FAIR_LINE_NUM	MAIN_MAIN_OID
	7 701	1240	02	Auto-PILR-	02/17/2021	1	73175
	7 701	1248	02	Auto-PILR-	01/15/2022	1	73176

OPAR_OPERATING_AREA_ID2	MAHT_MAIN_STUDY_CDE	MAHT_MAIN_SEQ_NUM	MAHT_MAIN_SUB_ID	COCO_COATING_COND_NME	COTP_CORROSION_TYPE_NME	FATP_FACILITY_TYPE_TXT
	7 701	1240	04	Good	None or Slight Surface	Main
	7 701	1248	03	Bare	None or Slight Surface	Main

LKLO_LEAK_LOCATION_NME	FAIR_NUM_OF_CLAMPS	LKCS_LEAK_CAUSE_NME	RPAC_REPAIR_ACTION_NME	PILR_REPLACED_FOOTAGE	FAIR_NUM_OF_ANODES	PILR_DEPTH_OF_COVER
Valve		1 Natural Forces	Other		0	36
Compression Coupling		1 Not Leak Related	Tightened		0	38

FIRS_STATUS_DTE	FAIR_REPAIR_DTE	PICL_PILR_CLASS_CDE3	PVTP_PAVING_TYPE_NME	FAIR_PAVING_DEPTH	PILR_COMMENT_TXT	FAIR_UPD_TS
44243.60829	44243.60829 R		MACADAM		8 leaking curb valve, renewed service moved meter in to out	44244.79442
44575.37931	44575.37931 R		MACADAM		6 2x2 ma cut tighten 2" st dresser	44576.79385