

CEN24LA070

**INVESTIGATION PHOTOGRAPHS**



**Photograph 1 - Helicopter Sitting Upright on Grass a After Accident (Courtesy of FAA)**



**Photograph 2 - Substantial Damage to The Top of Tailboom (Courtesy of FAA)**



**Photograph 3 - Closeup of Substantial Damage to Top of Tailboom (Courtesy of FAA)**