



Photo 1 – main wreckage (FAA)



Photo 2 – main wreckage, right wing view (FAA)



Photo 3 – engine and propeller damage (FAA)