



Photo 1 – Main wreckage, left wing view inverted (FAA)



Photo 2 – main wreckage, front view inverted (FAA)



Photo 3 -tire marks in soft sand (FAA)




Photo 4 -




Photo 5 -




Photo 6 -




Photo 7 -




Photo 8 -




Photo 9 -




Photo 10 -




Photo 11 -




Photo 12 -




Photo 13 -




Photo 14 -




Photo 15 -




Photo 16 -




Photo 17 -




Photo 18 -




Photo 19 -




Photo 20 -