



Investigative Photographs

Peter Wentz
Air Safety Investigator
Eastern Region Aviation

ERA19FA154

May 15, 2020



Photograph 1¹ – Exemplar photograph of the accident airplane – right side view.



Photograph 2 – Accident site – Photograph taken looking towards the northeast.

¹ Photograph provided by airplane owner.



Photograph 3 – Accident site – Photograph taken looking towards the north.



Photograph 4 – Accident site – Photograph taken looking towards the west.



Photograph 5 – Accident site – Photograph taken looking towards the South.



Photograph 6 – Accident airplanes tail section.



Photograph 7 – Accident airplanes engine.