




Investigative Photographs

Peter Wentz
Air Safety Investigator
Eastern Region Aviation

ERA19LA186

September 18, 2020



Photograph 1¹ – Accident airplane being removed from residences.

¹ Photograph provided by the Federal Aviation Administration.




Photograph 2² – Damaged nose and propeller.



Photograph 3³ – Damaged propeller.

² Photograph provided by the Federal Aviation Administration.

³ Photograph provided by the Federal Aviation Administration.



Photograph 4⁴ – Instrument panel.

⁴ Photograph provided by the Federal Aviation Administration.