



Investigative Photographs

ERA21LA151

Peter Wentz
Air Safety Investigator
Eastern Region Aviation



Photograph 1¹ – Accident airplane – right side view.

¹ Photograph provided by airplane owner.



Photograph 2² – Accident airplane – left side view



Photograph 3³ – Accident airplane – front view.

² Photograph provided by airplane owner.

³ Photograph provided by airplane owner.



Photograph 4⁴ – Accident airplane – left side horizontal stabilizer damage.

⁴ Photograph provided by airplane owner.



Photograph 5⁵ – Accident airplane – left side horizontal stabilizer close up damage.

⁵ Photograph provided by airplane owner.