



Investigative Photographs

ERA21LA254

Peter Wentz
Air Safety Investigator
Eastern Region Aviation



Photograph 1¹ – Accident airplane – left side view.



Photograph 2 – Accident airplane – left side view.

¹ Photograph provided by airplane owner.



Photograph 3 – Accident airplane – left side view.



Photograph 4 – Accident airplane – front view



Photograph 5 – Accident airplane – quartering front view.



Photograph 6 – Accident airplanes – right side view.



Photograph 7 – Accident airplanes – aft view.