



Investigative Photographs

ERA21LA100


January 4, 2021

Peter Wentz
Air Safety Investigator
Eastern Region Aviation



Photograph 1¹ – Accident airplane – left side view.

¹ Photograph provided by Pilot/owner



Photograph 2² – Accident airplane, fuselage damage.

² Photograph provided by Pilot/owner