



Photo 1 – Digital Photograph From Insurance Adjuster. Right Forward Quartering View of the Airplane Depicting the Right Side of the Airplane, and Structural Damage to the Right Wing.