



Photo 1 – FAA Digital Photograph. Left Side View of the Airplane at the Accident Site.



Photo 2 - FAA Digital Photograph. Right Rear View of the Airplane at the Accident Site. Note the Structural Damage to the Right Wing.



Photo 3 - FAA Digital Photograph. Frontal View of the Airplane at the Accident Site Depicting Nearly the Entire Airframe Except Outer Portion of the Left Wing. Note the Structural Damage to the Right Wing.



Photo 4 - FAA Digital Photograph. Frontal Right View of the Airplane at the Accident Site Depicting the Right Wing and Right Side of the Fuselage. Note the Structural Damage to the Right Wing.