



Photo 1 – Digital Photograph From Airport Manager. Right Side View of the Airplane where it Came to Rest. Note the Proximity to the Runway in the Background and the Structural Damage to the Right Wing.



Photo 2 - Digital Photograph From Airport Manager. Left Forward Quartering View of the Airplane at the Accident Site.



Photo 3 - Digital Photograph From Airport Manager. View of the Inboard Portion of Left Wing and Left Side of a Portion of the Fuselage. Note the impact Damage on the Leading Edge of the Left Wing Near the Wing Root.



Photo 4 - Digital Photograph From Airport Manager. Left Side View of the Airplane at the Accident Site.