



Photo 1 – Photo of skid marks leading off the active runway into a ditch.



Photo 2 – View of airplane at rest in the ditch.



Photo 3 – View of the airplane after recovery from the ditch showing structural damage to the nose of the airplane.