

ERA23FA200

INVESTIGATIVE PHOTOS



Photograph 1 - main wreckage, inverted view left side



Photograph 2 - Airplane view, inverted right side