

ERA24FA300

INVESTIGATIVE PHOTOS



Photograph 1 - Main wreckage in pond before recovery



Photograph 2 - Main wreckage, inverted after recovery from pond



Photograph 3 - Right wing