

ERA22FA058

**INVESTIGATION PHOTOGRAPHS**



**Photograph 1 - Forward view of aircraft at wreckage site.**



**Photograph 2 - View of left side aft of aircraft.**



**Photograph 3 - Left side forward view of aircraft wreckage.**



**Photograph 4 - Forward view of the right side of the aircraft wreckage.**



**Photograph 5 - View of vertical stabilizer and rudder.**



**Photograph 6 - View of left side rear of aircraft wreckage.**



**Photograph 7 - View of top of engine after removed from mud crater.**