

Iron Maiden

At Antonio Flores Start washing Combing off
5th side of Pilot House deck upon finish washing
Best rust and that's when Hole appeared was no Hole
in Cabin while washing flat Bar. Boat Crew was fire
watching in Blower trunk on Both sides where Nethali
Blanco washed off Port side flat Bars. This was at
about 7:00 AM to 9:00 AM in the morning when we finished

Foreman at allied shipyard
Boarded vessel when it arrive at yard to Put Blowers
and Blower Bags on fuel Tanks in Generator Room and
Backdeck fuel Tanks, fire cloth was already on 2th generator
and had inserts that was already cut out and
welded from another yard where vessel come from.