

Atmos Energy Corporation - Show Compliance/Construction Order Details

Business: 3405
70
Miss - eAM

Asset:
LEAK845961

Order# - Done - Status - Type:
29147866 - Start - 11/20/2024 - LKRV

Job Code:
LKRV

Display Normal

Display Debug

ReSet

Order Description Leak Re-Evaluation 3 Cc5073

Run Time: 01/29/2024 17:52

Job Details

Status Released Type:	Office: JACKSON-MS	Done:	Source:
Region: SOUTHERN	SubRegion: Jackson	District: Jackson/Flora	In MA:

Schedule Data

Start Date: 11/30/2024	Base Date:	Interval: 0	Printed:	Print Date:
------------------------	------------	-------------	----------	-------------

Asset Description

Asset Group: LEAKS	Asset#: LEAK845961	Parent Asset#: LKS (5073)
Asset Description: 1138 SHALIMAR DR 3600000 JACKSON 28233206	Activity: LEAK REVAL 3 5073	
Owning Department: SC5073	Child Assets:	Status: Active

Location Physical Information

GPS Latitude: [REDACTED]	GPS Longitude: [REDACTED]	GPS Altitude:
Address: 1138 SHAL MAR DR	Time Zone:	State: MS
Town/City: 3600000 JACKSON	Cross Street:	DST:
City Limits: Other Cross street castle hill dr		
Map Number: 28049 HINDS		Class Location: 3
Property Tax Code: 25185 HINDS, JACKSON, JACKSON -SSD		Control Code:
Description: City		Certificate of Occupancy Required:

Location Additional Information

WorkArea/SubArea: MSJACKW_C	PipeLine #:	Read Sequence:
Station Number:	Printer Name: noprint	Corrosion Section:
System Number:		Project Number:
Pipeline Balance Code:		Task Number:
Operation Area: MSJAX	Rate Division: 170	Facilities Classification: DIST
Retirement Unit Name: Non Unitized Retirement Unit		Zip:
Leak Survey Area: LKSURV5410	Original Work Order: 28233206	

Leak Data

Date Found: 2023/12/01 11:10	Time Classified: 11:10:00	Leak Grade: 3
Leak Grade By: CW362280 McBride, Shaun	Grade 2 Interval:	CGI Reading: 4
Apparent Location: MA N	Population Density: RES	Unit of Measure: % GAS
Ft To Building: 34	Surface Type: DIRT	
Leak Location: Below ground at main and service t	Leak Repaired: N	Leak Located (LKFD - 2): 2 - Below Ground

(LKRV) Leak ReEvaluation Completion Data

Comments & Labor

Atmos Energy Corporation - Show Compliance/Construction Order Details

Business: 3405
70

Asset:

Order# - Done - Status - Type:

Job Code:



Order Description **Leak Re-Evaluation 3 Cc5073**

Run Time: 01/29/2024 17:52

Data Entry Stats	Order#		
	29147866		
Asset Created:	12/01/2023	By: 8247	EAMADMIN
Order Created:	12/01/2023	By: 8247	EAMADMIN
Q. Results Entered:		By:	

ET	.317 Minutes	RECORD Count	0
----	--------------	--------------	---