



Eric Alleyne
ASI
ERA-AS

Date: 12/17/2021

Subject: ERA22LA089, Construction Site Camera video

Contact: Chris Carey
Executive Account Manager - Amazon
W.G. Yates & Sons Construction Company

This video was obtained from the W.G. Yates & Sons Construction Company site camera. The documented video captures the airplane descending as the CAPS parachute is being deployed. Additionally, the video shows smoke arising from the other side of a building, presumed to be the airplane that crashed.