

**TOTAL
TIME IN
SERVICE**

Description of Inspections, Tests, Repairs and Alterations
Entries must be endorsed with Name, Rating and Certificate Number of Technician
Repair Facility. (See back pages for other specific entries.)

11 MAY 2023 N239WD S/N:0392 TTSN: 32.1
Comply with **AIRFRAME** 25 Hour / Annual condition inspection.
Comply with FAR 14 CFR 43 Appendix D and CFR 91 207 (d). ELT
Battery expires April 2027. I certify that this aircraft has been
inspected on in accordance with Scoda 25 hour compliance
inspection procedures using the manufacturers maintenance
manual section 12.5 and found to be in airworthy condition after
the following inspection items were completed. Retorqued wing
mounting bolts. Retorqued all engine mounting bolts. Lubed all
flight controls. **END**

Russell M. Ziegler, LSRM-A [REDACTED]
[REDACTED]

[Handwritten Signature]

Description of Inspections, Tests, Repairs and Alterations

Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

11 MAY 2023 N239WD S/N:0392 TTSN: 32.1
Complied with Scoda Service Instruction SI_SPLS_005 Landing Gear Position Alert - G3X System. Conducted check of system. No issues noted and aircraft found to be in airworthy condition. **END**
Russell M. Ziegler, LSRM-A [REDACTED]

[REDACTED]