

Marathon Pipe Line LLC

Aerial Photographs of Edwardsville, Illinois Oil Spill Response Operations

PLD22FR002

March 12 – 15, 2022





*Figure 1. Leak source area, Cahokia Creek, Edwardsville, Illinois. March 13, 2022, 8:09 a.m.*





*Figure 2. Division 1 leak site, Cahokia Creek, Edwardsville, Illinois. March 13, 2022, 8:11 a.m.*





*Figure 3. Division 1, source area operations. March 13, 2022, 08:20 a.m.*





*Figure 4. Division 1, oil-contaminated wetland south of oil spill release source. March 12, 2022, 12:10 p.m.*





*Figure 5. Division 1, Cahokia Creek at Old Alton-Edwardsville Road, March 13, 2022, 08:17 a.m.*





*Figure 6. Division 2, Cahokia Creek at Wanda Road bridge. March 12, 2022, 5:05 p.m.*





*Figure 7. Division 3, Cahokia Creek at Oldenburg Road. March 12, 2022, 4:29 p.m.*





*Figure 8. Division 3, Cahokia Creek at Oldenburg Road. March 12, 2022, 2:57 p.m.*





*Figure 9. Division 4, oil boom site east of Oldenburg Road. March 12, 2022, 1:28 p.m.*





*Figure 10. Division 4, oil boom sites west of SR 3 on Cahokia Creek. March 12, 2022, 1:26 p.m.*





*Figure 11. Division 4 oil boom on Cahokia Creek, East of Mississippi River. March 12, 2022, 1:09 p.m.*





*Figure 12. Division 4, oil boom site on Cahokia Creek east of the Mississippi River. March 12, 2022, 1:10 p.m.*





*Figure 13. Confluence of Cahokia Creek and the Mississippi River. March 12, 2022, 1:08 p.m.*





*Figure 14. Source area remediation activities and pipeline reconstruction. March 14, 2022, 3:43 p.m.*





*Figure 15. Division 1 impacted wetland cleanup operations, March 15, 2022, 3:27 p.m.*