



## **MEMORANDUM FOR RECORD**

Investigative Photographs

**Peter Wentz**  
**Air Safety Investigator**  
**Eastern Region Aviation**

---

Date: October 30, 2019  
NTSB Accident Number: ERA20FA021



**Photograph 1 – Accident site.**




**Photograph 2 – Accident site.**



**Photograph 3 – Accident site - Interior.**



**Photograph 4 – Accident site.**



**Photograph 5 – Engine, left side.**



**Photograph 6 – Engine, right side.**



**Photograph 7 – Engine, aft under side.**



**Photograph 7 – Forward engine and propeller.**



**Photograph 8 – Aft right-side engine.**



**Photograph 9 – Vacuum pump.**



**Photograph 10 – Vacuum pump engine mount.**



**Photograph 11 – Disassembled vacuum pump.**



**Photograph 12 – Left wing layout.**



**Photograph 13 – Right wing layout.**