



The National Transportation Safety Board

Office of Aviation Safety
Central Region
Memorandum for the Record
Video Review Summary
CEN19FA270
New Orleans, Louisiana
August 16, 2019

A video that was recorded by a Fox 8 news cameraman was provided to the NTSB IIC for review. The video was proprietary to Fox 8.

Summary:

The video showed the airplane's ground runup, taxi for takeoff, and takeoff. The video ends while the airplane appeared to be established on a left downwind for runway 36. On takeoff, the airplane's tailwheel appeared to stay on the ground longer than usual. At liftoff, the airplane veered to the right a bit and began to climb out. The airplane then made a left turn to what appeared to be a downwind for runway 36. The video showed the airplane in level flight on the downwind.

Alexander Lemishko

[REDACTED]

Senior Air Safety Investigator
NTSB Central Region Aviation