



Motor Carrier Attachment 24:

NJSP Driver/ Vehicle Roadside Inspection Report

Cranbury, NJ; 06/07/2014

HWY14MH012

(2 pages)

DRIVER/VEHICLE EXAMINATION REPORT

Aspen 2.14.1.1



NEW JERSEY STATE POLICE
TRANSPORTATION SAFETY BUREAU
PRINCETON, NJ 08540
 Phone: () Fax: ()

Report Number: NJSPDP002367
Inspection Date: 06/11/2014
Start: 8:19:00 AM ET End: 1:36:00 PM ET
Inspection Level: | - Full
HM Inspection Type: None

WAL-MART TRANSPORTATION LLC

BENTONVILLE, AR 72716-0650
 USDOT#: 00063585 Phone#: ()
 MC/MX#: 311233 Fax#: ()
 State#:
 Location: GEORGES TOWING
 Highway: NJTPK
 County: MIDDLESEX, NJ

Driver: ROPER, KEVIN J
License#: () State: GA
Date of Birth: ()
CoDriver:
License#: State:
Date of Birth:
Shipper:
Origin: BRISTOL, PA Bill of Lading:
Destination: PERTH AMBOY, NJ Cargo: EMPTY

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	CVSA #	CVSA Issued #	OOS Sticker
1	TT	PTRB	2011	OK	()	0-2568	1XPHD49X6BD1()	50,000			
2	ST	GDAN	2003	OK	()	77397	1GRAA06253D4()	68,000			

BRAKE ADJUSTMENTS

Axle #	1	2	3	4	5
Right	1	1 3/8	1 1/2	1 1/2	1 3/4
Left	1 1/4	1 1/8	1 5/8	1 1/2	2
Chamber	C-20	C-30	MM	L-30	L-30

VIOLATIONS

Vio Code	Section	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
392.3-FPROP	392.3	D	Y	SP5424287	N	N	Fatigue - Operate a property-carrying CMV while impaired by fatigue. As per driver's statement after the crash, "I fell asleep"
395.15C	395.15(c)	D	N		N	N	Onboard recording device improper form and manner. Driver records deliveries /"drop & hooks" as off duty, not on duty not driving.
396.5A-HNLOW	396.5(a)	2	N		N	N	Hubs - Oil and/or Grease Leaking from hub - inner wheel seals leaking on both left and right side of axle 4.

HazMat: No HM Transported. **Placard:** No **Cargo Tank:**

Special Checks: Post Crash

Pursuant to NJAC 13:60 (Federal Motor Carrier Safety Regulations Parts 390, 391, 392, 393, 394, 395, 396, 397) and NJAC 16:49 (Title 49 Code of Federal Regulations Parts 171, 172, 173, 177, 178, and 180). I hereby notify and declare KEVIN ROPER named on this report OUT OF SERVICE. No motor carrier shall permit or require this driver to drive or operate any motor vehicle until 10 hours.

The undersigned certifies that all OOS violations noted on this report have been corrected and action taken to assure compliance with New Jersey Law, Federal Motor Carrier Safety and Hazardous Material regulations insofar as they are applicable to motor carriers and drivers on the highways of this state.

Signature Of Repairer X: _____ Facility: _____ Date: _____

NOTE TO DRIVER: This report must be furnished to the motor carrier whose name appears on this report.

NOTE TO MOTOR CARRIER: The undersigned certifies that all violations noted on this report have been corrected and action taken to assure compliance with New Jersey Law, Federal Motor Carrier Safety and Hazardous Material regulations insofar as they are applicable to motor carriers and drivers on the highways of this state. Please sign the certification below and return this report within fifteen days to: New Jersey State Police, 3925 US Hwy. 1 Princeton, N.J. 08540 . ATTN: Hazardous Materials

Signature Of Motor Carrier X: _____ Title: _____ Date: _____

Report Prepared By:
 TPR ()

Badge #:
 6509

Copy Received By:
 KEVIN ROPER

Page 1 of 1



00063585 NJ NJSPDP002367

X _____

X _____