



**MOTOR CARRIER FACTORS ATTACHEMENT**

**Motor Carrier Photos 1-16**

**Randolph, NH**

**HWY19MH010**

(9 pages)



**Photo 1.** Exemplar Westfield Transport Vehicle. Same, year, make and model as accident vehicle.



**Photo 2.** This exemplar trailer is the make, model, year as the trailer involved in the crash that was towed by the accident truck.



**Photo 3.** Exemplar Truck and Exemplar Trailer. These vehicles are the same make, model, and years as the combination vehicle involved in this crash.



**Photo 4.** Westfield Transport Vehicle / frame with mounted 5<sup>th</sup> Wheel.



**Photo 5.** Westfield Transport Vehicle.



**Photo 6.** East Transport Vehicle Parked with Westfield Transport Vehicles



**Photo 7.** East Transport Vehicle Parked with Westfield Vehicles.



**Photo 8.** 3 Brothers Tansport Vehicle Parked with Wesfield Transport Vehicles




**Photo 9.** Dad Transportation Vehicle Parked with Westfield Transport Vehicles



**Photo 10.** Dad Transportation Vehicle Parked with Westfield Transport Vehicles.



**Photo 11.** Massachusetts State Police Inspecting Westfield Transport Vehicles



**Photo 12.** Massachusetts State Police Weighing Westfield Transport Vehicle



**Photo 13.** Massachusetts State Police Weighing Westfield Transport Vehicle



**Photo 14.** Massachusetts State Police Weighing Westfield Transport Vehicle





**Photo 15.** Massachusetts State Police and USDOT conducting an inspection on Westfield Transport Vehicle



**Photo 16.** This photo shows Westfield Transport lettering removed from vehicle 3 weeks after the crash.