

DATE 19__	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
N489C		AIRFRAME	TACH 2613.11	TTAF 3587.61 12-11-20

PACKED ALL WHEEL BEARINGS. REBUILT LEFT MAIN GEAR ACTUATOR, SERVICED SYSTEM WITH 5606. PERFORMED RETRACTION OPS AND LEAK CHECK OK. INSPECTED AND LUBED ALL FLIGHT CONTROLS. ELT BATTERY WAS INSPECTED I/A/W FAR 91-207(d). ELT BATTERY DUE DATE IS 4/2021. ALL AD'S CHECKED TO DATE. THIS AIRFRAME WAS INSPECTED I/A/W AN ANNUAL AND WAS FOUND TO BE IN AIRWORTHY CONDITION.

ANTHONY F. DAIUTO
A&P IA