

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: CEN19FA144
--	---------------------------------------

For Use In All Modal Investigations

OFFICE Aviation Safety	DATE OF ACCIDENT 5/18/19	ACCIDENT LOCATION (City & State) Chillicothe OH
EVIDENCE OBTAINED BY: E Malinowski		
<input checked="" type="checkbox"/> EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION E Malinowski on scene	DATE 5/18/19
<input type="checkbox"/> EVIDENCE RECEIVED FROM:		GROUP Powerplant
EVIDENCE CONTROL NUMBER CEN19FA144 - PWR - 1		
DESCRIPTION (<input type="checkbox"/> BIN ITEM - HAS BEEN SEPARATED <input type="checkbox"/> Engine FADEC and speed sensor		

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: R.	LAST NAME: Talbot
ADDRESS: [REDACTED]	Chicago, IL 60661
PHONE: [REDACTED]	EMAIL: [REDACTED]
RETURNED <input checked="" type="checkbox"/>	DATE: 9/3/19
CONTACT: Mr. Talbot	

CHAIN OF CUSTODY

RELEASED BY: E. Malinowsk, NTSB through AMF	RELEASED TO: Continental Motors, Analytical	DATE: 5/22/19
PURPOSE: Examination at Continental via UPS # [REDACTED] arrived 5/28/19		
RELEASED BY: Continental Motors, P. Grice	RELEASED TO: AMF, C. Ferraraccio [REDACTED]	DATE: 9/3/19 11/14/19
PURPOSE: Return to recovery company AMF via UPS [REDACTED] arrived 09/04/2019 at 1029		
RELEASED BY: *****	RELEASED TO: *****	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		