

#### **Motor Carrier Attachment**

NYSDOT July 2014, January 2015, and June 2015 inspections of accident stretch limousine while operated by RLS Limousines of the Capital District

Schoharie, NY October 6, 2018

**HWY19MH001** 

(5 pages)

MC 300e (08/05)

# NYSDOT PASSENGER AND FREIGHT SAFETY DIVISION BUS SAFETY INSPECTION PROGRAM

DATE 07/30/2014

START TIME 13:58

MILEAGE 175901

				REGION 01		
OPERATOR NO.: 46256	ASSIGNED MVI	:		MVI NO.:	IN TRANS	
ASSIGNED OP. NO.:	TYPE(S) OF SERVICE	6	INSPECTION	COUNTY: 001	BUS N	ю.: 16
OPERATOR NAME: RLS LIMOUSINES	OF THE CAPITAL DIST.			ANTED as /30/2014	LAST NYSDO	T INSPECTION
MAILING ADDRESS: 137 LARK STREE	T					7/30/2014
CITY: ALBANY		STA	TE: NY ZIP: 122	10	MILEAGE: 1	
OPERATOR TEL#	NVODOTNO				CERT NO.: J	842085
ICC/MC NO.:	NYSDOT NO.:	USDC	OT NO.:		EXPIR. DATE:0	1/30/2015
Vehicle Information VIN	LICENSE NO.	STATE	HORSEPOWER	BODY M	IODEL NUMBER	YEAR 2001
1FMNU40S51EB FMVSS CODE VEH. CLASS VEH. 3 6 0	TYPE SERVICE CO	DDES	REG. COUNTY FUEL 1			
CE	ATTACHED OUTET	2) [0] \( \( \( \) \)		ICODA ATIO	NI	
	ATTACHED SHEET(S	5) FUR VI		FORMATIO	IN	
TYPE OF INSPECTION:  0. RANDOM • 1. REGULA		_	IPORARY OUT OF SER		EET INSPECTION ON-PRESENT	0 8. OTHER
LAST COMPANY INSPECTION DATE	07/27/2014		Mil	EAGE 1758	350	9. INITIAL
STOPPING SERVICE: 576 MEASUREMENTS:	PARKING BRA	000	OTHER:	EAGE 1758	DIAMOND Saf TYPE:	
STOPPING SERVICE: 576	PARKING BRA PERFORMAN	000			DIAMOND Saf	ety Only Portio
STOPPING SERVICE: 576 MEASUREMENTS: CERTIFICATE 1942095 EXPIRA	PARKING BRA PERFORMAN  O1/30/2015  NUMBER OF THE PERFORMAN  O1/30/2015  NUMBER OF THE PERFORMAN  NUMBER OF THE PERFORMAN  PERFORMAN  PERFORMAN  NUMBER OF THE PERFORMAN  PERFORM	OOS MBER: ions17 NY used to cany vehicle the follow	OTHER:  END TIME: 14:  CRR 720.11 any vehicarry passengers until trecord that is without ving conditions:	de with a Defe he defect(s) h a Defect rating	DIAMOND Saf TYPE: n  COMPLETE IN  ect Rating of "A" s as been repaired g of "A" discovered or to carrying pass	ety Only Portio  USPECTION  hall be issued /corrected and d at the time  sengers;

MC 300e (08/05)

MOTOR VEHICLE INSPECTOR SIGNATURE

## NYSDOT PASSENGER AND FREIGHT SAFETY DIVISION BUS SAFETY INSPECTION PROGRAM

DATE 01/08/2015

START TIME 09:53

MILEAGE 177935

Out-of-State Inspection? REGION 01 IN TRANSIT PERMIT NO. **OPERATOR NO.: 46256** ASSIGNED MVI: MVI NO.: INSPECTION COUNTY: 001 TYPE(S) OF SERVICE 6 ASSIGNED OP. NO.: BUS NO.: 16 **GRANTED** as OPERATOR NAME: RLS LIMOUSINES OF THE CAPITAL DIST. **B&C STATUS**: LAST NYSDOT INSPECTION of 1/8/2015 MAILING ADDRESS: 137 LARK STREET DATE: 07/30/2014 CITY: ALBANY ZIP: 12210 STATE: NY MILEAGE: 175901 **OPERATOR TEL: CERT NO.: J842085** ➤ ICC/MC NO.: NYSDOT NO. **USDOT NO.:** EXPIR. DATE: 01/30/2015 Vehicle Information VIN LICENSE NO. STATE HORSEPOWER **BODY MODEL NUMBER** YEAR 285 **EXCURSION LIMO** 1FMNU40S51EB NY 2001 REG. COUNTY FUEL TYPE GVWR SEATS WHEELCHAIR SPACES FMVSS CODE VEH. CLASS VEH. TYPE SERVICE CODES 3 13080 00 0 L SEE ATTACHED SHEET(S) FOR VEHICLE DEFECT INFORMATION TYPE OF INSPECTION: 2. REINSPECTION ○ 4. TEMPQRARY OUT OF SERVICE ○ 6. FLEET INSPECTION ○ 8. OTHER ● 1. REGULAR ○ 3. ACCIDENT ○ 5. PERM OUT OF SERVICE O. RANDOM 9. INITIAL 7. NON-PRESENT LAST COMPANY INSPECTION DATE 01/07/2015 **MILEAGE** 177916 PARKING BRAKE 000 DIAMOND Safety Only Portio STOPPING OTHER: SERVICE: 551 PERFORMANCE: TYPE: **MEASUREMENTS:** CERTIFICATE **EXPIRATION** OOS **END ✓** COMPLETE INSPECTION K959515 07/08/2015 10:24 NUMBER: NUMBER: TIME: Pursuant to NYSDOT Bus Passenger Vehicle Safety Regulations17 NYCRR 720.11 any vehicle with a Defect Rating of "A" shall be issued an "out of service vehicle" sticker, and that vehicle may not be used to carry passengers until the defect(s) has been repaired/corrected and the vehicle has been re-inspected by a NYSDOT inspector. Any vehicle record that is without a Defect rating of "A" discovered at the time of inspection shall be issued an inspection certificate based on the following conditions: (A) If the vehicle has one or more Defect ratings of "B", all such defect(s) must be repaired by the carrier prior to carrying passengers; (B) If the vehicle has only one or more Defect ratings of "C", all defect(s) must be repaired by the carrier within 15 days of the date of inspection. THIS REPORT IS ACCURATE AND COMPLETE:

COPY RECEIVED BY

MC 300e (08/05)

# NYSDOT PASSENGER AND FREIGHT SAFETY DIVISION BUS SAFETY INSPECTION PROGRAM

DATE 06/25/2015 START TIME 10:13

MILEAGE 179609

☐ Out-of-State	Inspection?			REGION 01	IN TRANSIT
OPERATOR NO.:	46256	ASSIGNED MVI	No. 1864	MVI NO.:	PERMIT NO.
ASSIGNED OP. NO.:		E(S) OF SERVICE 6	INSP	ECTION COUNTY: 00	BUS NO.: 16
	RLS LIMOUSINES OF THE		B&C STAT	US: of 6/25/2015	LAST NYSDOT INSPECTION
MAILING ADDRESS:	The second secon	A STATE OF THE STA		ZIP: 12210	DATE: 01/08/2015 MILEAGE: 177935
OPERATOR TEL	-14				CERT NO.: K959515
ICC/MC NO.	: NYSDO	r-NO.	USDOT NO.:	3	EXPIR. DATE: 07/08/2015
Vehicle Information		NOTICE NO.	ATE LIOPSEE	OWED BODY	MODEL NUMBER YEAR
1FMNU40S5	4114	LICENSE NO. ST	ATE HORSEF 285		ON LIMO 2001
FMVSS CODE VE	H CLASS VEH TYPE O	SERVICE CODES	REG. COUNTY		SEATS WHEELCHAIR SPACES 18 00
The second secon	SEE ATTAC	HED SHEET(S) FO	R VEHICLE DEF	ECT INFORMATION	ON
STOPPING		ACCIDENT 5	PERM OUT OF SE	RVICE 7. N	LEET INSPECTION () 8. OTHER ON-PRESENT () 9. INITIAL 406 DIAMOND TYPE:
MEASUREMENTS: CERTIFICATE	EXPIRATION	PERFORMANCE:		ND	✓ COMPLETE INSPECTION
NUMBER:	DATE:	NUMBER:	212242 TI	ME: 11:07	W COMPLETE INSPECTION
an "out of service ve the vehicle has beer of inspection shall be A) If the vehicle has	ehicle" sticker, and that veh	nicle may not be used DT inspector. Any vertificate based on the form of the f	to carry passenge nicle record that is ollowing conditions ct(s) must be repa	rs until the defect(s) he without a Defect ration it ired by the carrier pri	
MOTOR PHICLE IN	SPECTOR SIGNATURE	MVI NO	COPY RECEI	VED BY	

### **Defect Report**

Operator Number:

46256

Inspection Date: 06/25/2015

Bus Number:

16

	1.00	
INSPECTION ITEM NO.	OUT OF SERVICE	DEFECTS DISCOVERED
53.00	N	
34.01	A	Steering Pump/Fluid Level/Leaks:3. Any leak at shaft seal ,,,,, p.s. pump seal is leaking ,,,,,
31.02	С	Ext Body Panel Corrosion:3. Small rust holes in panels or members that has not met the above described condition (recommended Repair would include corrective applications designed to prevent further corrosion)
99.02	N	Other Non OOS Defect Not Listed Or Regulation non Compliance: ,,,,, exhaust pipe rubbing on gas tank, needs to be addressed,,,,,,
		3
		·
	Ï	
	;	
		·