

Update Service Order at 185 BRISTOL BLVD , JACKSON , MS

First Name:    
 Last Name:    
 Full/Org Name / Business Partner #:  1002087531   
 Street Number / Name / Unit Number: 185 BRISTOL BLVD    
 City / State / Zip code: JACKSON MS 39204-3507   
 Telephone Number:

Order: 100024599028   
 Service Order Type: Emergency   
 Service Order Activity: Leak Investigation Order

- Get Appointment
- Book Appointment
- Override Appointment
- Plumber Appointment

Appointment Details

Status ■

Service Order

100024599028

Start Date: 11/20/2023   
 Order Descr: Leak Investigation Order

Start Time: 02:07 PM   
 Contact Person:    
 Inside Work By:

End Date: 11/20/2023   
 Contact Number: 6013724808   
 Charge: 0.00

End Time: 03:52 PM

Service Order Notes:

XST: RAYMOND RD , LOC: NEAR WTR MTR OUTSIDE , OUT.  
 SOMEONE HAD BEEN WORKING IN THE AREA & NOW STRONG SMELL GAS NEAR WTR MTR  
 NO DOGS  
 FEE WAIVE: NO

.....1.....2.....3.....4.....5.....6.....7..  
 XST: RAYMOND RD , LOC: NEAR WTR MTR OUTSIDE , OUT.  
 SOMEONE HAD BEEN WORKING IN THE AREA & NOW STRONG SMELL GAS NEAR WTR MTR  
 NO DOGS  
 FEE WAIVE: NO  
 TECH COMPLETION NOTES:  
 // SN 11-20-23/R-2869 ARVED ONSITE CHKCED MTR WITH CGI FOUND 0% BH RISER  
 ,SVR AND FOUND 0%. CHCKED SWR AND 360 ARND HOUSE FOUND 0% BH BOTHSIDES O  
 F DWAY AND FOUND 0%. BH MAIN AND FOUND 80% LEL ON SVR TIE IN FOR ADDRESS  
 190. BH THE REST OF MAIN AND FOUND 0% THERE IS NO MIGRATION, THE LEAK H  
 AS ALREADY BEEN GRADED BY A PERVIOUS TECH. ADV BP AND LEFT SAFE NO UPM T  
 EST NEED NEVER TURNED GAS OFF //

Order:

Sys.Status:

HeaderData   Operations   Components   Costs   Partner   Objects   Additional Data   Location   Planning   Control   Enhancement

Information

Completion Information

Contact Number: <input type="text" value="[REDACTED]"/>	Contact Name: <input type="text" value="[REDACTED]"/>	Exception for Office Review: <input type="button" value="v"/>
Latitude: <input type="text" value="[REDACTED]"/>	Apt Type: <input type="button" value="N No Appointment v"/>	Additional Forms: <input type="button" value="v"/>
Longitude: <input type="text" value="[REDACTED]"/>	Dunning Amount: <input type="text"/>	Investigation: <input type="button" value="v"/>
Contract Account: <input type="text" value="003013524838"/>		Warning Tag: <input type="button" value="v"/>
Unattached Emergency Indicator: <input type="button" value="v"/>		Tech Waive Fee: <input type="button" value="v"/>
Project Number: <input type="text"/>		Appliance Lit: <input type="button" value="v"/>
		CSA Waive Fee: <input type="button" value="v"/>

Investigation

Method	Repairs Advised	Leak Location	Leak Location 2	Inside/Out
<input type="text" value="DETECTOR"/>	<input type="text" value="NO"/>	<input type="text" value="NO LEAK FO"/>	<input type="text"/>	<input type="button" value="v"/>
Tested for CO: <input type="button" value="N v"/>	Odorant Detectable: <input type="button" value="Y v"/>	Customer Not at Home: <input type="button" value="v"/>	Meter Loop Action	
Customer Warning: <input type="button" value="N v"/>	Appliance Work: <input type="text" value="NONE"/>		<input type="text" value="N/A"/>	
Bar Test Sewer Y/N	<input type="button" value="Y v"/>	Remarks: <input type="text" value="0%"/>	Detector Serial Number	
Bar Test Company Facility Y/N	<input type="button" value="Y v"/>	Remarks: <input type="text" value="0%"/>	<input type="text"/>	
Bar Test Customer Facility Y/N	<input type="button" value="Y v"/>		Outside Ambient Level	
			<input type="text"/>	
			Inside Ambient level	
			<input type="text"/>	
			Ambient Level with Appliance Operating	