

Park Avenue Sink-Hole and Water Main Break Video by Con Edison

The video show a sink hole on southbound Park Avenue, between East 116th and East 117th, which revealed water main break after the accident, with water aggressively spraying within the opened hole on March 12, 2014.¹

¹ Appendix B3.MPG