



Photo 1 – Aerial View of Glider Location (Photo Courtesy of Operator)



Photo 2 – Map View of Glider Location (Photo Courtesy of Operator)



Photo 3 – Aerial Closeup of Glider (Photo Courtesy of Operator)



Photo 4 – Damage to Wing (Photo Courtesy of Operator)



Photo 5 – Damaged Fuselage of Glider (Photo Courtesy of Operator)



Photo 6 – Damaged Tail (Photo Courtesy of Operator)