



Photo 1 – View of the left aileron damage. Courtesy of the FAA.



Photo 2 – View of the left wing and aileron. Courtesy of the FAA.



Photo 3 – View of the left main landing gear. Courtesy of the FAA.



Photo 4 – View of the left wing. Courtesy of the FAA.