



Photo 1 – Accident Airplane

Photo courtesy of FAA



Photo 2 – Airplane ready for examination




Photo 3 – Loose wire (Magneto)



Photo 4 - Magneto