



Motor Carrier Photos 10 -11:

“4” Way Driver Logs

Cranbury, NJ; 06/07/2014

HWY14MH012

(3 pages)



Photo 10: This photo depicts driver logs and receipts that were found in the cab of Vehicle 6 that was operated by "4" Way Transportation. The driver's log for trip date 6/5/14 was found torn into pieces.




Photo 11: This photo shows trip activity on 6/5/14 for the driver of Vehicle 6 involved in this accident.