



**Photo 1 – View of photo of airplane showing left outboard wing damage.**



**Photo 2 – View of left wing showing structural damage**