



NTSB ERA22LA145

N29VA, EUROCOPTER DEUTSCHLAND GMBH, MBB-BK 117 C-2

Photo Array



Photo 1: Overview of the helicopter and dolly (Photo Courtesy of Virginia State Police)



Photo 2: Overview of the helicopter and damaged sustained (Photo Courtesy of Virginia State Police)



Photo 3: Overview of the helicopter's left side and damaged sustained (Photo Courtesy of Virginia State Police)



Photo 4: Overview of the helicopter's right side and damaged sustained (Photo Courtesy of Virginia State Police)



Photo 5: Overview of the dolly and separated spotlight (Photo Courtesy of Virginia State Police)



Photo 6: Overview of the helicopter's left side and damaged sustained (Photo Courtesy of Virginia State Police)