



Photo 1 –Removal of accident airplane from accident site. Photo provided by the Operator.



Photo 2 – Left front view of accident airplane after removal from accident site. Photo provided by the Operator.



Photo 3 – Left side empennage view of accident airplane after removal from accident site. Photo provided by the Operator.