



Photo 1 – View of left side showing fuselage buckling



Photo 2 – View of front of airplane showing collapsed main gear