



Photo 1 – Accident Site with Tire Marks Leading to the Airplane Wreckage



Photo 2 – Airplane Wreckage Front View



Photo 3 – Airplane Wreckage Rear View