



Photo 1 – Left Wing Damage (Source: FAA)



Photo 2 – Left Horizontal Stabilizer Damage (Source: FAA)