



**Photo 1 – Damage to Left Wing (Source: FAA)**



**Photo 2 – Closeup of Damage to Left Wing (Source: FAA)**