



Photo 1 – Portion of Separated Tail boom Laying in Mature Corn Field (Source: FAA)



Photo 2 – Remnants of Wire Embedded in Wreckage (Source: FAA)



Photo 3 – Closeup of Remnants of Wire Embedded in Wreckage (Source: FAA)