

**NTSB ERA22LA011**

N121YT, Flight Design GMBH CTLS

Photo Array



Photo 1: View of the airplane as found at Atlanta Air Salvage (Photo Courtesy of Rotax)





Photo 2: View of the oil thermostat and oil hoses. (Photo Courtesy of Rotax)





Photo 3: Number 1 rocker cover with metallic debris inside. (Photo Courtesy of Rotax)






Photo 4: View of the number 3 cylinder head. (Photo Courtesy of Rotax)



Photo 5: Number 3 cylinder with metallic debris and no oil. (Photo Courtesy of Rotax)





Photo 6: Number 3 connecting rod bearing, connecting rod, and piston (Photo Courtesy of Rotax)