

NTSB ERA23LA018

N62368, Cessna 310R

Photo Array



Photo 1: View of the airplane's right side at the accident site. (Photo Courtesy of FAA)



Photo 2: View of the airplane's left side at the accident site. (Photo Courtesy of FAA)



Photo 3: View of damage to the airplane's left horizontal stabilizer (Photo Courtesy of FAA)