



Photo 1 – View of left side of airplane inverted showing cockpit crushing



Photo 2 – View of right side of airplane inverted showing horizontal stabilizer and elevator buckling